

Notice to Mariners

No. 1 of 2025

Port of Clarence River (Yamba) – Hickey Leads Decommissioned

Please be advised that the Hickey Leads have been decommissioned.

- Hickey Island Rear Lead Spar. 29° 25.785'S 153° 21.374'E **Removed**.
- Hickey Island Forward Lead Spar. 29° 25.775'S 153° 21.392'E. Day shape and light **replaced** with Special Mark Yellow Cross Day Shape and Light. *Fl. Y. 5s*

Buoys established in the following positions.

- Port Hand Buoy. *Fl. R. 3s* 29° 25. 650'S 153° 21. 678'E
- Port Hand Buoy. *Fl. R. 3s* 29° 25. 758'S 153° 21. 468'E
- Starboard Hand Buoy. *Fl. G. 3s* 29° 25. 705'S 153° 21. 479'E

Additional References - Nil

Charts Affected: AUS 222

Harbour Master Office- Newcastle & Yamba

05 August 2025



YAMBA | NEWCASTLE | SYDNEY | PORT KEMBLA | EDEN

www.portauthoritiesnsw.com.au